

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4301	DATE	July 20, 2018
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO.,LTD (JAPAN)		
DESCRIPTION OF DEFECT	As for the fuel pump on shovel loaders(wheel shovel), abnormal contact will be happened electrically because of unsuitable structure of motor brush inside the pump. Cause of abnormal working of the fuel pumps,the engine may be stopped and does not start again in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF	REMARKS
YDR-LADA	ZX125W-6	2017	106	
		TOTAL	106	