

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4323	DATE	Aug 23, 2018
MANUFACTURER	Hino Motors,Ltd. FURUKAWA UNIC CORPORATION		
DESCRIPTION OF DEFECT	With fuel tank for car carrier, when attaching check valve for air-taking to the fuel tank, double O ring is attached to the check valve by mistake and that leads to a possibility that there is not enough air-intake in the fuel tank. Therefore, when the fuel tank continues to be used, it gets dented because of negative pressure inside it by supplying fuel into engine and in the worst case, the supply of fuel to the engine stops, and that could disable car from running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-XZU720M	HINO DYUTRO	2018	7
2KG-XZU720	TOYOTA DYNA	2018	2
TOTAL			9