## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	4319	DATE	Aug.29 2018
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In the relevant heavy-duty trucks, the fastening bol mounting hardware are not tightened properly because hardware were not controlled adequately during the m If the vehicle continues to be used in this condition, the hardware may loosen and, in the worst case, the battery	perly because the dimensions of the during the manufacturing process. condition, the fastening bolts of the	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FY70HY	「FUSO SUPER GREAT」	2017	1
		TOTAL	1