

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4320	DATE	Aug.29 2018
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In the relevant medium-duty trucks, one of the four fastening bolts for the urea tank mounting hardware is not installed because the instruction of the installation work was inappropriate. If the vehicle continues to be used in this condition, the fastening bolts of the hardware may loosen and, in the worst case, the urea tank will fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FK61F	「FUSO FIGHTER」	2017~2017	12
2KG-FK62FZ		2017~2017	2
2KG-FK62FY		2017	1
2KG-FK64F		2017~2017	2
		TOTAL	17