

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2711	DATE	August 30 , 2018
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	The hollow shaft seal cannot keep original seal function due to very progressive deterioration. Depending on the state of shaft surface, seal might not be robust enough because of seal material and a very progressive wear of the seal may happen. Very few oil leakages can happen between seal and hollow shaft surface. Oil will leak inside clutch housing and small drops can fall on the floor through bottom clutch housing water draining hole.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-RH5F	「LUTECIA」	2013	757
ABA-RM5M	「LUTECIA R.S.」		279
		TOTAL	1,036