VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

	0 : 0710	DATE	1 01 0010		
RECALL No.	Gai-2712	DATE	Aug. 31, 2018		
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)				
DESCRIPTION OF	Mustang, Door Latch Replacement				
DEFECT	Concern Description:				
	In the affected vehicles, the pawl spring tab in a side door latch may				
	break. This condition will typically prevent the door from latching. In certain situations where the door is able to be closed, the door may				
	unlatch while driving, increasing the risk of injury.				
	Dealer Action:				
		•	atches on affected vehicles with		
	updated parts. Th	nis service must b	e performed at no cost to the		
	customer.				

	COMMERCIAL	MODEL	NUMBER OF
TYPE	NAME	YEAR	VEHICLE
		RECALLED	
Unknown	Mustang	2015	346 units
		TOTAL	346 units