

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4314	DATE	August 31. 2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	At the starter switch harness in self-propelled reaping and threshing machine (combine harvester), the routing of the harness is improperly, when the steering is operated, the harness is contacted with the link in the steering column. Using in that condition, harness is damaged by steering operation, it might result in stopping engine because the harness short circuit and it cuts a fuse and the supply of fuel is cut off in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「AJ217」	2009~2014	1,430	
-	「AJ219」	2009~2014	1,539	
	「AJ319」	2009~2014	788	
C22B	「AJ223」	2009~2014	976	
C32D	「AJ323」	2009~2014	2,328	
			TOTAL	7,061