

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4317	DATE	August 31. 2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	At the brake switch of agricultural tractor, the waterproof of the switch is improperly, water intrudes in the switch, which results in a conduction failure. Therefore, brake lamp may not light up or remain lit. Also, the brake interlocking function of the transmission does not operate normal and it may cause to stop due to the turning operation during work, or travel stops despite not stepping on the brake, or it needs to step clutch to stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「EG221」	2012~2014	381
		2014~2015	199
		2014~2015	50
	「EG223」	2012~2014	446
		2014~2015	299
	「EG225」	2012~2014	1,782
		2014~2015	1,525
		2014~2015	153
	-	「EG227」	2007~2012
「EG230」		2007~2012	1,423
-	「EG228」	2012~2013	900
		2014~2015	754
	「EG231」	2012~2013	760
		2013~2015	618
		2013~2015	188
-	「EG224」	2007~2012	2,533
TOTAL			14,282