

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4324	DATE	Sep 3, 2018
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	On emergency vehicles, due to the insufficient design of the siren amplifier power switch, when operating the power switch, the switch may remain pressed and do not return to original position. If this condition may occur, the siren amplifier does not work, resulting the rooftop beacon lights and the siren may become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MH34S	WAGON R	2016	4
DBA-HA36S	ALTO		2
DBA-ZC72S	SWIFT		19
DBA-ZD72S			18
CBA-TDA4W	ESCUDO	2015~2017	9
		TOTAL	52