

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2709	DATE	Sep. 5, 2018
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>A software error may cause the instrument cluster to fail for a few seconds and then restart. In some cases, the MMI screen may fail at the same time and then restart.</p> <p>A software update must be performed on the vehicles affected.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4GCREB	A6 allroad	2017	35
ABA-4GCREC	A7 SB 3.0Tq	2017	82
ABA-4GCRES	A6 3.0Tq A6 Avant 3.0Tq	2017	21
ABA-4GCTGA	S6 S6 Avant	2017	22
ABA-4GCTGL	S7 SB	2017	28
ABA-4GCWUC	RS7 SB	2017	52
ABA-4GCWUS	RS6 Avant	2017	34
ABA-4GCYGG	A6 1.8T A6 Avant 1.8T	2017	23
ABA-4GCYPC	A7 SB 2.0Tq	2017	295
ABA-4GCYPS	A6 2.0Tq A6 Avant 2.0Tq	2017	355
		Total	947