

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4327	DATE	Sep.5.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>Due to insufficient consideration about assembly variation on engine wire harness, a portion of the wire harness could contact a surrounding part. In this condition, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, then an electrical short circuit could occur between the damaged wires and generate heat, and in the worst case, vehicle fire could occur.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZVW50	[Prius]	2015-2018	215,921
DAA-ZVW51			113,099
DAA-ZVW55			62,593
DLA-ZVW52	[Prius PHV]	2016-2018	33,630
DAA-ZYX10	[C-HR]	2016-2018	128,627
		TOTAL	553,870