

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	4331	DATE	11th - September -2018	
MANUFACTURER	Yano Special Vehicle Co., Ltd. 4-2-1 Kaminofukita Shingu Kasuya-Gun, Fukuoka 811-0123 Japan			
DESCRIPTION OF DEFECT	A crack occurs by the vibration when running, because it's lacking in the strength of the mounting hardware in a fuel tank of a refrigeration refrigerator car. Therefore when being worst when a fuel tank is slant and the use is continued in the state which is just as it is, mounting hardware is damaged, and there is a fear that a fuel tank is omitted.			
TYPE	COMMERCIAL NAME	MODEL TEAR RECALLED	NUMBER OF VEHICLE	
QKG-FE7JPAA	RANGER	2013	1	
QKG-FQ1EWBG	PROFIA	2013	1	
QKG-FR1EXBG		2013	1	
QKG-FR1EXBJ		2014	1	
QKG-FR1EZBG		2014	1	
PK-FW1EXWG		2011	1	
SKG-FRR90S2		FORWARD	2012	1
TKG-FRR90S2	2012		1	
PKG-FSR34S2	2008		1	
PDG-FTR34T2	2007~2010		5	
QKG-FTR34T2	2013		1	
QKG-CYJ77AA	GIGA		2013	1
QKG-CYL77A		2013	2	
QKG-FS54VZ	SUPER GREAT	2013	3	
QKG-FS55VZ		2012	2	
BDG-FU54JZ		2009	1	
LKG-FU54VZ		2012	1	
PJ-FU55JZ		2006~2007	3	
BDG-FU55JZ		2007	1	
BKG-FU55JZ		2008	2	
LKG-FU55VZ		2011~2012	5	
QKG-FU55VZ		2013~2014	19	
QPG-FU65VZ		2015	1	
PKG-CG4ZE		QUON	2010	2
LKG-CG5ZA			2011	1
QKG-CG5ZA			2012~2014	5
QKG-CG5ZE			2012~2015	4
			TOTAL 68	