

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2724	DATE	September.13, 2018
MANUFACTURER	Thai Honda Mfg.Co.,Ltd.		
DESCRIPTION OF DEFECT	Because of inappropriate procedure for assembling the wire harness to the frame, the wire harness may have been damaged during assembly. In this case, a break can occur in the wire harness through frequent repetition of steering whereby the headlights, brake lights, turn signal indicators, speedometer and horn could fail to function properly or the engine could stall and refuse to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MD44	「CRF250L」 「CRF250M」	2018	130
		TOTAL	130