

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2725	DATE	August xx, 2018
MANUFACTURER	General Motors LLC		
DESCRIPTION OF DEFECT	Because of low tolerance against temperature and humidity, driving mechanism of electric steering lock, ECL, may be stuck and ECL cannot be unlocked under hot temperature and high humidity condition. When ECL isn't unlocked, ECU doesn't allow to start the engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-X245A ABA-X245S -X245A- -X245S	Corvette Corvette Z16 Corvette Z06 Corvette ZR1	2009 – 2013	227
		TOTAL	227