VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4332	DATE	Sep.27, 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to improper assembling of the camera covers in vehicle manufacturing process, some of them obstruct a part of a visual field of the sensor camera which performs automatic light distribution control for vehicle headlight. Therefore, there is a possibility that the affected vehicles fail to have sufficient upper angle of the sensor detection area stipulated by the safety standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-SK9	「FORESTER」	2018	48
		TOTAL	48