

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4341	DATE	Oct.4 2018
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some electric light-duty trucks, the mounting bolts for the circuit board in the power distribution unit, which supplies power from the high voltage battery, are inappropriately tightened. Due to vibrations during running or other causes, the bolts may loosen. If this happens, the electrical resistance and the temperature of the fastening point can increase. In the worst case, the internal parts of the power distribution unit can be burned and lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-FEB80 KAI	「FUSO CANTER」	2018~2018	28
		TOTAL	28