

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2731	DATE	Oct. 10, 2018
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Moisture may enter the electronic components and cause the overheating and failure of the additional coolant pump. As a result, localised smoulder damage cannot be ruled out. In individual cases, this may cause the vehicle to catch fire.</p> <p>Replacing the additional coolant pump if necessary and software update of the engine control unit.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8KCDNA	A4 Allroad	2013	232
DBA-4GCDN	A6 2.0/ A6 Avant 2.0	2014	299
DBA-8FCDNF	A5 Cabriolet 2.0Tq	2012 – 2017	401
DBA-8KCDN	A4 2.0T/ A4 Avant 2.0T	2013 – 2015	11,938
DBA-8KCDNF	A4 2.0Tq/ A4 Avant 2.0Tq	2013 – 2015	5,518
DBA-8TCDNF	A5 2.0Tq	2012 – 2016	649
DBA-8TCDNL	A5 SB 2.0Tq	2012 – 2016	6,228
		Total	25,265