VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

 CAMPAIGN No.
 GAI-2732
 DATE
 Oct. 10, 2018

 MANUFACTURER
 Audi
 (Japanese Importer: Audi Japan KK)

 DESCRIPTION OF
 Fluctuations in the tightening torque of the bolts securing the fuel rail. Individual bolts may loosen over time.

 DEFECT
 The bolted connections for the fuel rail must be tightened.

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8WCVN	A4 1.4T	2017-2018	1,175
		Total	1,175