

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 3 4 2	DATE	O c t . 1 0 . 2 0 1 8
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	A tightening torque to be loaded on the nut of a portion fastening an oil hose on the engine oil circulating path to the oil tank had been set inadequately, so that some of the tightening torques loaded on the nut on the relevant portion have been insufficient. We have a concern, therefore, that engine oil will leak from the relevant portion owing to the impaired airtightness caused by the fluctuation in pressure or others of the engine oil circulating path.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RH03J	SR400	2009~2017	8,905
		TOTAL	8,905