

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2729	DATE	October 12, 2018
MANUFACTURER	General Motors LLC		
DESCRIPTION OF DEFECT	<p>With inappropriate calibration of EPS module software, a temporary loss of EPS assist followed by a sudden return of EPS assist, particularly during low-speed turning maneuvers, could occur. The loss and sudden return of EPS assist typically happens within a 1 second period and is caused by an electrical/software issue.</p> <p>Affected vehicles will have EPS module software reprogrammed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
N/A	Cadillac Escalade	2015	87
		TOTAL	87