

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	2739	DATE	October 23, 2018
MANUFACTURER	SUZUKI MOTOR CORPORATION (Japanese Importer : SPK CORPORATION)		
DESCRIPTION OF DEFECT	<p>Due to improper design of sealing construction of fuel pump fitting on fuel tank, the O-ring on fuel pump may be twisted during the fuel pump installation on the fuel tank.</p> <p>In this condition, it may lead to reduce sealing ability by internal pressure changes in fuel tank, in the worst case, may leak fuel out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DM11A	GSX-R1000	2017-2018	330
DM11G	GSX-R1000R	2017-2018	650
		TOTAL	980