

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 3 5 7	DATE	O c t . 3 0 . 2 0 1 8
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	A containing amount in the material of a breather hose that connects the radiator with the reservoir tank had been inadequate, so that some of the hoses concerned have short durability. Consequently, one of the hoses concerned may become worse rapidly and cracks may appear on it, and in the worst case, there is a real danger that coolant leaks from a cracked portion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2 B K - S G 3 7 J	TRICITY MW150A	2 0 1 6 ~ 2 0 1 8	2, 7 5 0
2 B J - S E C 1 J	TRICITY MW125	2 0 1 7 ~ 2 0 1 8	5 6 0
	TRICITY MW125A	2 0 1 7 ~ 2 0 1 8	3 2 6
		TOTAL	3, 6 3 6