

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4362	DATE	Nov. 1st, 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate calculation program on combination meter control unit, low fuel warning light may not be illuminated at the regulated remaining fuel amount, and driving range on remaining fuel function of the combination meter display may also indicate excessive drivable range against actual remaining fuel amount. Therefore, if a driver determines that the vehicle is still drivable and continues to drive, it may run out of gas and stall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BN9	「LEGACY」	2017	1903
DBA-BS9		2017	6742
		TOTAL	8645