VEHICLES SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	外-2740	DATE	November 9 .2018		
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.				
DESCRIPTION OF DEFECT	In the exhaust device of the agricultural tractor, since the method of fixing the clamp connecting the exhaust pipe is inappropriate, tightening of the clamp is loosen. As a result, there is a possibility that a gap is formed in the connecting portion of the exhaust pipe, the untreated exhaust gas leaks, and the exhaust gas does not conform to the safety standard. In the worst case, the exhaust pipe comes off, burning the wire harness around the exhaust pipe, in the worst case a fire may occur.				

TYPE	COMMERCIAL NAME		_ YEAR \LLED	NUMBER OF VEHICLE
_	「JD-6095MC」 2016 ~ 2017		~ 2017	11
-	「JD-6105MC」 2016 ~		~ 2017	108
	「JD-6115MC」 2016 ~ 20		~ 2016	3
	「JD-6095RC」	D-6095RC」 2016 ~ 2016		4
	「JD-6105RC」	2016 ~	~ 2017	9
	「JD-6115RC」	2016 ~ 2017		17
			TOTAL	152