

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

<b>CAMPAIGN No.</b>	4368	<b>DATE</b>	November 9, 2018
<b>MANUFACTURER</b>	SUZUKI MOTOR CORPORATION		
<b>DESCRIPTION OF DEFECT</b>	<p>Due to inappropriate criteria and manufacturing control of component (element) on the headlight control circuit board, some of elements may not have enough durability. For this reason, the elements may be broken by electrical current for headlight operation and the headlight may not turn on. In the worst case, fuse for lights may blow and all electrical lights may not turn on.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
2BJ-DV12B	SWISH	2018	2,034
		<b>TOTAL</b>	<b>2,034</b>