

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4372	DATE	Nov 15, 2018
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to improper construction of the engine auxiliary belt, the durability of the belt may be insufficient and the belt may break down with the resonance fracture. If belt breaks down, the alternator and the water pump become inoperative with the warning lamp turned on. In the worst scenario, engine may stall and may not restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-HA35S	ALTO	2013~2014	48,818
DBA-MH34S	WAGON R		170,139
DBA-MF33S	MR WAGON		12,027
DBA-MK32S	SPACIA		136,828
DBA-MR31S	HUSTLER		20,804
DBA-MG33S	MOCO		28,757
DBA-HB35S	CAROL		6,414
DBA-MJ34S	FLAIR		18,138
DBA-MM32S	FLAIR WAGON		16,394

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MS31S	FLAIR CROSSOVER	2014	2,897
		TOTAL	461,216