

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4373	DATE	Nov 15, 2018
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper program for detecting the error in the electric power steering controller, it may mistakenly detect the error when the engine is started or the engine is re-started by auto-idle stop function with low battery voltage situation. In such case, the power steering warning lamp will be illuminated and the steering assist function will be deactivated, resulting in the loss of the steering assist and the increase of the steering operation force.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MH34S	WAGON R	2012~2015	394,444
DAA-MH44S		2014~2015	69,469
DBA-MJ34S	FLAIR	2012~2015	38,087
DAA-MJ44S		2014~2015	5,118
		TOTAL	507,118