VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4374	DATE	Nov. 1	15. 2018
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the coolant device for heavy-duty-trucks, due to improper fitting of the radiator lower hose, some of the clearance between the radiator lower hose and the engine under cover is insufficient. Hence if the radiator lower hose expands while the engine under cover is vibrating from engine idling, the hose and the cover may come into contact, and may damage the hose. If the vehicle continues operation under these conditions, the hose may crack and cause coolant water leakage, ultimately leading to overheating of the vehicle in the worst case.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LDG-CD5ZE LKG-CD5ZE QKG-CD5ZE QPG-CD5ZE	Quon	2010 - 2017	708	
		TOTAL	708	