

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2752	DATE	Nov. 21, 2018
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Oil leakage may occur at the gearbox breather when the vehicle is being driven on a racetrack and extreme driving maneuvers are being undertaken. As a result, smoke may be produced and a vehicle fire cannot be ruled out..</p> <p>The single breather pipe for the gearbox breather system must be replaced by a dual breather pipe.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4SCSPD	Audi R8 V10 plus	2016-2017	90
ABA-4SCSPF	Audi R8 V10		102
		Total	192