

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2756	DATE	November.29, 2018
MANUFACTURER	Honda Vietnam Co., Ltd.		
DESCRIPTION OF DEFECT	Because the stop switch locating groove in the brake lever bracket is inappropriate in size, the stop switch may, if it is deformed through repetition of swelling with rainwater or the like and subsequent contraction, get jammed in the locating groove in the bracket. Should this happen, the brake lights would remain on with the brake lever released.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-AF75	「TACT」	2014-2015	37,774
		TOTAL	37,774