

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4382	DATE	November 29 ,2018
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the rocker arm shafts of the light-duty truck engines, some attachment bolts are loose because their tightening torques are insufficient. Therefore, if the drivers keep driving the trucks without repair, these loose bolts might fracture and make abnormal noise. In the worst case, the trucks might stall while they are in motion and end up failing to restart.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-NHR85A TPG-NHR85AN TRG-NHR85A TRG-NHR85AN	[ELF]	2015-2016	4,099
TPG-NHS85A TPG-NHS85AN TRG-NHS85A TRG-NHS85AN		2015-2016	2,443
TPG-NJR85A TPG-NJR85AD TPG-NJR85AN TPG-NJR85N TRG-NJR85A TRG-NJR85AN TRG-NJR85N TSG-NJR85PAN		2014-2016	14,260
TPG-NJS85A TPG-NJS85AN TRG-NJS85A TRG-NJS85AN		2014-2016	1,776
TPG-NKR85A TPG-NKR85AD TPG-NKR85AN TPG-NKR85AR TPG-NKR85N TPG-NKR85R TRG-NKR85A TRG-NKR85AN TRG-NKR85AR TRG-NKR85N TRG-NKR85R TSG-NKR85KAN		2014-2016	15,927

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-NKR85YN TPG-NKR85YN	[ELF]	2014-2016	1,844
TKG-NKS85A TKG-NKS85AD TKG-NKS85AN TPG-NKS85A TPG-NKS85AN		2014-2016	2,532
TPG-NLR85AN TPG-NLR85AR TPG-NLR85N TRG-NLR85AN TRG-NLR85AR TRG-NLR85N TSG-NLR85PAN		2014-2016	8,353
TPG-NLS85AN TPG-NLS85AR TRG-NLS85AN TRG-NLS85AR		2014-2016	330
TPG-NMR85AN TPG-NMR85AR TPG-NMR85N TPG-NMR85R TRG-NMR85AN TRG-NMR85AR TRG-NMR85N TRG-NMR85R TSG-NMR85AN TSG-NMR85KAN TSG-NMR85N		2014-2016	7,031
TKG-NMS85AN TKG-NMS85AR TPG-NMS85AN TPG-NMS85AR		2014-2016	815
TPG-NNR85AN TPG-NNR85AR TPG-NNR85N TRG-NNR85AN TRG-NNR85AR		2014-2016	762
TPG-NNS85AR TRG-NNS85AR		2014-2016	58
TPG-NPR85AN TPG-NPR85AR TRG-NPR85AN TRG-NPR85AR TSG-NPR85AN		2014-2016	14,751
TKG-NPR85YN TPG-NPR85YN		2014-2016	5,971

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-NPS85AN TKG-NPS85AR TPG-NPS85AN TPG-NPS85AR	[ELF]	2014-2016	1,047
TRG-LHR85A TRG-LHR85AN	[TITAN]	2015-2016	1,390
TRG-LHS85A TRG-LHS85AN		2015-2016	326
TPG-LJR85AD TPG-LJR85AN TRG-LJR85A TRG-LJR85AN TRG-LJR85N		2014-2016	695
TPG-LJS85AN TRG-LJS85A TRG-LJS85AN		2014-2016	67
TPG-LKR85AD TPG-LKR85AN TPG-LKR85N TPG-LKR85R TRG-LKR85A TRG-LKR85AN TRG-LKR85AR TRG-LKR85N TRG-LKR85R		2014-2016	577
TKG-LKR85YN		2016	1
TKG-LKS85AD TKG-LKS85AN TPG-LKS85A TPG-LKS85AN		2014-2016	84
TRG-LLR85AN TRG-LLR85AR TRG-LLR85N		2014-2016	157
TRG-LLS85AR		2014-2016	13
TPG-LMR85AN TPG-LMR85N TPG-LMR85R TRG-LMR85AN TRG-LMR85AR TRG-LMR85N TRG-LMR85R		2014-2016	145
TPG-LMS85AN TPG-LMS85AR		2015-2016	10
TRG-LNR85AR		2014-2016	87

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TRG-LNS85AR	[TITAN]	2015-2016	6
TPG-LPR85AN TPG-LPR85AR TRG-LPR85AN TRG-LPR85AR		2014-2016	372
TKG-LPR85YN TPG-LPR85YN		2014-2016	113
TPG-LPS85AN TPG-LPS85AR		2014-2016	28
		TOTAL	86,070

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TRG-NHR85AN	[ELF]	2017	2
TPG-NHS85AN		2017	1
TSG-NMR85N		2016	1
		TOTAL	4

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
4JJ1 ENGINE	5-87100932-0 5-87100936-0 8-98256672-0 8-98256683-0	2016-2017	6
		TOTAL	6