

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4384	DATE	Nov. 29. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the engine control unit of the buses, due to the control program of the data storage memory is inappropriate, some of the data necessary for driving may be lost. Therefore, the engine warning lamp may turn on, and in the worst case, there is a possibility that the engine can not be started.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-KV290N2 2KG-KV290N2	[HINO Blue Ribbon]	2017~2018	117
2DG-KV290Q2 2KG-KV290Q2 2PG-KV290Q2 2TG-KV290Q2		2017~2018	99
2KG-KR290J3	[HINO Rainbow]	2017~2018	166
		TOTAL	382