

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4386	DATE	November 29, 2018	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	<p>With regards to the shock absorber, due to inappropriate management for the tightening of the lower bolts which fix the shock absorbers to the front axle(s) and/or the upper bolts/nuts which fix the shock absorbers to the rear axle(s), some of the bolts/nuts torque may be insufficient and may become loose. Thus, if the vehicle continues operation under these conditions, the bolts/nuts may come off and one side of the shock absorber may be disconnected. In such cases the disconnected shock absorber may interfere with surrounding parts which may cause abnormal noise. Ultimately, the contacted parts may be at risk to be damaged.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5AL	Quon	2017	5	Front only 5
2PG-CD5BA		2017 - 2018	56	Front only 27 Rear only 1 All 28
2PG-CD5BL		2017 - 2018	56	Front only 56
2PG-CD5CA		2017 - 2018	957	Front only 549 Rear only 36 All 372
2PG-CD5CE		2018	60	Front only 1 Rear only 2 All 57
2PG-CD5CL		2017 - 2018	84	Front only 84
2PG-CG5BA		2017 - 2018	9	Front only 5 Rear only 1 All 3
2PG-CG5BL		2018	1	Front only 1
2PG-CG5CA		2017 - 2018	1721	Front only 970 Rear only 126 All 625
2PG-CG5CE		2018	55	Rear only 7 All 48
2PG-CG5CL		2017 - 2018	77	Front only 77
2PG-CW5AL		2017 - 2018	471	Front only 471
2PG-CW5BL		2017 - 2018	96	Front only 96
2PG-CW5CA		2017 - 2018	76	Front only 33 Rear only 2 All 41
2PG-CW5CL 2PG-CW5CLKai		2017 - 2018	115	Front only 115
2PG-CX5BA		2017 - 2018	25	Front only 12 All 13
2PG-CX5BL		2017 - 2018	17	Front only 17
2PG-GK5AAB		2017 - 2018	301	Front only 158 Rear only 7 All 136
2PG-GK5AAD		2017 - 2018	131	Front only 42 Rear only 1 All 88

2PG-GK5AAE

2017 - 2018	9	Front only 1 Rear only 1 All 7
TOTAL	4322	Front only 2720 Rear only 184 All 1418