

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic vehicles

CAMPAIGN No.	4387	DATE	November 29, 2018	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	<p>With regards to the fuel device for heavy-duty tractors, because the molding applied to the bracket which holds the fuel tank was inappropriate, the side guard bracket fixed to the fuel tank bracket became slanted and the clearance between the fuel tank base and the side guard bracket may become insufficient. Thus, the side guard bracket may come into contact with the fuel tank base and if the vehicle continues operation under these conditions, the fuel tank may be damaged and there might be a risk of fuel leakage in the worst case.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-GK5AAB	Quon	2017 - 2018	16	
2PG-GK5AAD		2017 - 2018	12	
2PG-GK5AAE		2018	14	
		TOTAL	42	