

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4388	DATE	November.29, 2018
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Because the stop switch locating groove in the brake lever bracket is inappropriate in size, the stop switch may, if it is deformed through repetition of swelling with rainwater or the like and subsequent contraction, get jammed in the locating groove in the bracket. Should this happen, the brake lights would remain on with the brake lever released.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-AF79	「TACT」	2016－2017	61,697
2BH-AF79		2017－2018	21,707
JBH-AF77	「Giorno」	2015－2017	26,291
2BH-AF77		2017－2018	4,907
		TOTAL	114,602