Domestic Vehicles

CAMPAIGN No.	4 3 9 3	DATE	Dec. 4. 2018	
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD			
DESCRIPTION OF DEFECT	Some of light duty dump trucks have too small space between stay of hydraulic hose for tipping operation and rear brake pipe, and they can contact each other while driving. Therefore, using the vehicle without countermeasure, rear brake pipe can be damaged. At the worst case, and braking force can drop due to leak of break fluid caused by the damage.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-FBA30	FUSO CANTER	2017~2018	462
TPG-FBA60	- FUSU CANTER	2017~2018	1057
TRG-FBA3W	NISSAN ATLAS	2017~2018	24
TRG-FBA6W		2017~2018	13
TPG-FBA3Y	LID TRUOVO	2017	2
TRG-FBA3Y	UD TRUCKS Kazet	2018	2
TRG-FBA6Y		2017~2018	3
	•	TOTAL	1563