

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4394	DATE	4 December, 2018
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO. LTD.		
Causes and situations where the structure, device, or capacity is determined to be non-compliant with standards	Due to an insufficient gap between the hydraulic hose locking stay for dump operations and the rear wheel brake pipe on the small dump truck, vibrations while traveling may cause interference between the parts (the hydraulic hose locking stay for dump operations and the rear wheel brake pipe). As a result, continued use of the equipment in a state of interference would lead to damaging the rear wheel brake piping, and in the worst case, brake fluid may leak out and braking performance may decrease.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MITUBISHI FUSO	TKG-FBA30	CANTER	2018	1
	TKG-FBA60	CANTER	2017	2
	TPG-FBA30	CANTER	2017-2018	441
	TPG-FBA60	CANTER	2017-2018	984
NISSAN	TRG-FBA3W	ATLAS	2017-2018	6
	TRG-FBA6W	ATLAS	2017-2018	8
UD TRUCKS	TRG-FBA3Y	KAZET	2018	1
			TOTAL	1,443