

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4395	DATE	December.6, 2018
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Evaporative emission control system may have its canister charge tube routed improperly under inadequate work instructions. In this case, the tube may come into contact with the exhaust pipe whereby the tube may be carbonized. If the vehicle continues in service, the carbonized portion of the tube can suffer damage from vibrations during driving or otherwise and could leak fuel evaporative emission which could, in the very worst case, cause a vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-RC79	「VFR800F」	2017~2018	180
		TOTAL	180