

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4396	DATE	Dec. 6. 2018
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	<p>Due to improper routing of the rear brake hose and the rear wheel rotation sensor wire, they may touch the rear tire. Continued use may result in the following:</p> <ul style="list-style-type: none"> · The rear brake hose may become worn. In the worst case, this could create the potential for loss of braking performance due to brake fluid leakage. · The rear wheel rotation sensor wire may become worn. In the worst case, this could create the potential for turning on the ABS indicator light, not displaying the speed on the meter, and deactivating ABS function. 		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZR900C	Z900RS	2018	395	
		TOTAL	395	