VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2762	DATE	Dec. 10, 2018
MANUFACTURER	DUCATI MOTOR HOLDING SpA		
	(Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	Rear speed sensor cable could interfere with the chain sliding shoe		
	installed on the swingarm and the cable might fail. Therefore, the wiring		
	of the speed sensor is pressed during use, the wiring is disconnected,		
	and in the worst case, the speed display on the meter may not be		
	performed.		
	Check the wiring of the rear wheel speed sensor and replace the sensor		
	for those that are disconnected or those that have recorded error of the		
	rear wheel speed sensor.		
	If there is no problem wit	h the wiring, adjust	the layout handling. This will
	be performed free of cha	ırge	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DA00J	PanigaleV4	2018	68
2BL-DA00J	PanigaleV4S	2018-2019	175
2BL-DA00J	PanigaleV4Speciale	2018	26
		TOTAL	269