

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic vehicles

CAMPAIGN No.	4401	DATE	December 12, 2018	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the windshield wipers, the vehicle master control unit which controls windshield wiper operation has an inappropriate program. Whilst the wiper is in intermittent mode and the wipers are not in motion, if the user changes the wiper to Low-speed (Lo) mode, an arc discharge may occur at the wiper relay contact point. Thus, over current may occur in the wiper electric power supply circuit which may lead to burnt fuse . The windshield wiper may then become inoperable and that might result in reduced visibility.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5AL	Quon	2017 - 2018	10	
2PG-CD5BA		2017 - 2018	89	
2PG-CD5BL		2017 - 2018	101	
2PG-CD5CA		2017 - 2018	1,939	
2PG-CD5CE		2018	120	
2PG-CD5CL		2017 - 2018	146	
2DG-CF5AL		2018	20	
2PG-CG5BA		2017 - 2018	27	
2PG-CG5BE		2018	3	
2PG-CG5BL		2018	1	
2PG-CG5CA		2017 - 2018	3,369	
2PG-CG5CE		2018	138	
2PG-CG5CL		2017 - 2018	134	
2PG-CW5AL		2017 - 2018	759	
2PG-CW5BL		2017 - 2018	174	
2PG-CW5CA		2017 - 2018	121	
2PG-CW5CL 2PG-CW5CLKai		2017 - 2018	176	
2PG-CX5BA		2017 - 2018	49	
2PG-CX5BL		2017 - 2018	27	
2DG-CZ5BL		2018	110	
2PG-GK5AAB		2017 - 2018	747	
2PG-GK5AAD		2017 - 2018	334	
2PG-GK5AAE		2017 - 2018	58	
2PG-GK5AAK	2018	1		
		TOTAL	8,653	