VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import vehicles

CAMPAIGN No.		Gai-2759	DATE	December 13. 2018			
MANUFACTURER		Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)					
DESCRIPTION OF DEFECT	1	of LED and a printed circ lamp is activated along w then the brake lamp is tu lead to a faint flash of the With regards to heavy-du bellows of the exhaust pi the seams of the bellows	uit board inside of the tail vith either of the turning ir rned off, it may cause an brake lamp . uty tractors/trucks, due to pe, some exhaust gas co . Hence, the exhaust pipe se, the exhaust gas may	ctors, due to inappropriate choice lamp cluster, when the brake adicators or the hazard lamps and abrupt voltage change that might inappropriate material for the imponents may cause corrosion at e seams may crack due to engine leak and the exhaust gas leaked the exhaust pipe.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE		
QKG-H2TDA1		2014 - 2018	347	1&2 1only 2only	270 5 72
QKG-H2TEA1	FH	2014 - 2018	457	1&2 1only 2only	330 7 120
-H2TDA1-		2015 - 2018	4	1&2 2only	2 2
-H2TEA1-		2015 - 2018	22	1&2 2only	15 7
Unspecified		2014 - 2018	567	1&2 1only 2only	335 9 223
		TOTAL	1,397	1&2 1only 2only	952 21 424