

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4398	DATE	Dec.13 2018
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some large-sized route buses, since the painting process of the front axle was inappropriate, the radius rod mounting brackets were installed before the paint on the mounting surface was dried. Therefore, as the paint dries, the fastening bolts of the brackets can loosen. In the worst case, radius rods or shock absorbers may come off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-MP38FK	「FUSO AERO STAR」	2018	1
2KG-MP38FM		2018~2018	4
2PG-MP35FK		2018	1
2PG-MP38FK		2018~2018	5
2PG-MP38FM		2018~2018	2
		TOTAL	13