

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

**Domestic Vehicles**

<b>CAMPAIGN No.</b>	<b>4402</b>	<b>DATE</b>	<b>Dec.13.2018</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	<p>As the plastic material of outer race of tensioner pulley which adjusts the belt tension of power steering pump is improper, the plastic part may break down making abnormal noise.</p> <p>In the worst case, the steering may become heavy as the belt comes out from the pulley.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
<b>CBA-TD94W</b>	<b>ESCUDO</b>	<b>2006</b>	<b>19</b>
		<b>TOTAL</b>	<b>19</b>