

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4413	DATE	Dec.26.2018
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper control in manufacturing process,incorrect specification parts of front differential which has a different reduction ratio were installed to some of the vehicles in production.</p> <p>Therefore, a rotational speed difference between front and rear wheels occurred when driving a vehicle in 4WD mode. As the result, the driving performance may be deteriorated and the drivetrain parts may break and vehicle may become immobile in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-JB64W	JIMNY	2018	20
		TOTAL	20