

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4411	DATE	Jan. 10. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain trucks specialized for loading vehicles, due to the improper routing of the charge pipe between the air compressor and the air drier, the pipe concerned may be damaged in driving over bumps or applying stress while driving on a rough road. Therefore, the compressor air may leak and the warning light may be lit, resulting the braking force to decrease if the vehicle is continued to be used under the condition.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FG8JWAA	[HINO Ranger]	2010~2016	50
LDG-GK8JWAA		2010~2017	609
		TOTAL	659