## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles CAMPAIGN No. DATE January 16, 2019 4409 MANUFACTURER Mitsubishi Logisnext Co., Ltd **DESCRIPTION** In the forklift electric circuit, since the selection of the EGR valve relay is OF inappropriate, so that the coil of the relay is lack of durability in the DEFECT normal operating condition. As a result, the relay may be broken in short time and EGR keeps closing regardless the condition of the engine and in the worst case NOx may not be satisfied with Japanese exhaust emission standards.

| TYPE   | COMMERCIAL<br>NAME      | MODEL<br>YEAR<br>RECALLED | NUMBER OF<br>VEHICLES |
|--|-------------------------|---------------------------|-----------------------|
| YDM-F199<br>YDM-F200<br>YDM-F201<br>YDM-F202 | UNICARRIERS<br>FORKLIFT | 2018                      | 126                   |
|  |                         | TOTAL                     | 126                   |