VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.		DATE	Jan.	. 2019
MANUFACTURER	NICHIJO CORPORATION			
DESCRIPTION OF DEFECT	In the engine of the rotary snow plow, the gap between the cooling fan and the fan guard is inappropriate. When colliding with a street protrusion during snow removing work, the cooling fan and fan guard are brought into contact. In the worst case, the cooling fan may be damaged and fall on the road.			
ТҮРЕ	COMMERCIAL NAME	MODEL YEA RECALLED		NUMBER OF VEHICLE
YDS-R03F	「HTR308A」	2 0 1 8 R03F-0002∼ R03	3F-0075	4 8
		T	OTAL	4 8

[Notes] The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.