

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 4 1 8	DATE	J a n . 2 1 . 2 0 1 9
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>①Due to an inappropriate structure in the core wire of the rear wheel drive belt, some of the belts may lack strength. Therefore, a heavy load may be put on the said belt repeatedly because of a sudden acceleration, etc., and in the worst case scenario, the said belt may break and as a result, the vehicle may become unable to move.</p> <p>②Due to an inappropriate program in the engine control unit, when the throttle is opened slightly from the idling state, the air-fuel mixture which will be taken into the combustion chamber may become thin. Therefore, in the worst case scenario, the air-fuel mixture may lead to abnormal combustion, and as a result, an engine stall may occur.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2 B L - S J 1 5 J	XP 5 3 0 S A TMAX	2 0 1 7 ~ 2 0 1 8	1 1 3
	XP 5 3 0 D A TMAX		8 0 0
		TOTAL	9 1 3