

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2773	DATE	January 24. 2019	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	With regards to heavy-duty tractors with double rear-axle leaf suspensions, due to inappropriate tightening of the hexagon socket bolts which hold the leaf spring ends and the rubber springs, by driving vibration etc. the hexagon socket bolts may become loose and the leaf springs to be floated that may generate some abnormal noise. Thus, if the vehicle continues operation under these conditions, the hexagon socket bolts and the latches may come off after which the plate to be detached that might carry the risk of being an obstruction for other transportation.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
FH	Unspecified	2018	6	
		TOTAL	6	